

Oil Field Environmental Incident Summary

Incident: 20121208124937 **Date/Time of Notice:** 12/08/2012 12:44

Responsible Party: ConocoPhillips

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: CHSU 24C-3SH 16

Field Name: CEDAR HILLS

Well File #: 15953

Date Incident: 12/7/2012 **Time Incident:** 15:30

Facility ID Number:

County: BOWMAN

Twp: 131

Rng: 106

Sec: 3

Qtr:

Location Description: Along Flow line Right of Way approximately 1/2 mile south of the well pad

Submitted By: Lewis Schoenberger

Received By:

Contact Person: Lewis Schoenberger
PO BOX 51810
MIDLAND, TX 79710-1810

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Miles

Distance Nearest Water Well: 0.5 Miles

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	barrels	5	barrels	10	barrels
Brine	10	barrels	5	barrels	5	barrels
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/18/2016

Clean Up Concluded: 11/4/2013

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

A vacuum truck was dispatched to recover pumpable fluids. The impacted soil will be excavated and sent for appropriate disposal.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 12/10/2012 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to report, 20 bbls released (50-50 oil and brine) on pipeline right-of-way approximately 1/2 mile south from location. Follow up is necessary.

Date: 1/15/2013 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Inspected on site, this date. Hydro-vac crew exposed lines in same trench prior to excavation of contaminated soils and repair. Found another line in trench leaking on 1/4/13, and reported on 1/15/13. Roberts and Stockdill discussed situation on location with Bryce Lecoe. Hydro-vac exposure of lines is now SOP for Conoco before excavation and repair due to lack of knowledge of number and placement of underground lines in an area. All contaminated soils and all hydro-vac discharge will be sent to Petro-Comp for disposal.